

Pump Technology Bulletin

Market Segment: All Distributors

Issued By: Ryan Sura

Volume: PTI201802

Date: 1/16/18

Subject: Discontinuation of angled GRP guide claw

Dear Partners:

Please note that HOMA has discontinued use of the angled guide claw used in autocoupling part numbers 8604018 (1" guide rails) and 8604008 (1/2" guide rails). These part numbers are being replaced by 8604019 (1" rails) and 8604005 (1/2" rails) and will use a straight guide claw, as shown below (Figure 1).

With this assembly, the lifting point is through the central loop of the handle. **IMPORTANT: DO NOT** lift from the rear tab attached to the handle or the pump will bind on the guide rails during retrieval (Figure 2).



Figure 1



Figure 2

Upon special request, the angled guide claw can still be ordered, but must be ordered from Germany and will require additional lead time.

If you have any questions or concerns, please do not hesitate to contact us.

Sincerely,



Ryan Sura

Senior Application Engineer

Email: rsura@homapump.com

Phone: (203) 736-8890 ext. 252